50X1

3 February 1955

MEMORANDUM FOR: THE RECORD 50X1 Maintenance Visit to SUBJECT 50X1 50X1 On 27 January 1955 the undersigned visited for the purpose of repairing the ultrasonic 50X1 burglar alarm system installed by this division some three weeks ago at the above mentioned plant. After the unit had been operating satisfactorily for approximately one week, it failed to reset when the reset button was depressed. The contractor at this point shut the equipment down and notified TSS/FED of same. of FED 50X1 requested that APD send a man to the plant for the repair job. Upon arrival there, the undersigned examined the equipment and discovered a broken soldered connection. It was resoldered with dispatch, and the unit now performs satisfactorily. A permanent connector for this breakdown point will be prepared in the APD laboratory and installed in the near future. 50X1 50X1 TSS/APD Distribution: Orig. - Ad Hoc #15 TSS/FED - 1 TSS/S00 - 1 MH - 1DOCUMENTINO. . Chrono NO CHANGE IN CLASS. MH/br 1.1 DECLASSIFIED CLASS, CHANGED TO: TS NEXT REVIEW DATE: .. 切用: 超70/2 _REVIEWER: 037169